
## Teddy Pardo Eversolo Conversion Kit Quick Startup Guide



## What's included



Torx key






Step 2: place the device on its side, power entry socket facing upwards. Keep it on its side throughout the conversion process.

Remove 6 screws holding the back panel.






Step 3: Holding the top cover firmly, pull the bottom half slightly backwards and to the side.


- Do not use force.
- Keep the front side of the device as stationary as possible.
- Opening the device forcefully may break the front panel ribbon wires!

**Result of step 3**. note the fragile ribbon wires at the right side of the picture.

Make sure those wires are not overstretched, and in any case, do not touch those wires.










Result of step 5.




Step 7: Prepare the panel adapter and its two bracings.


Start by inserting the wire harness through the power entry opening.

Keep the device steady on its side.



Result of step 7







Result of step 9



Step 10: Close the top cover, reverse step 3, then step 2, then step 1

